

## Table 6 - Range Improvement Project Summary

(Last updated December 2001)

Listed projects are not in workable condition. Project Needs recommends action for the project, such as maintenance, abandonment (or removal), or total reconstruction.

**Table 6.1 Anderson Allotment (#01401)**

Project Name	Project Number	Condition	Project Needs
South Toppin Butte Pit	723889	Fair	Remove and rehabilitate area

**Table 6.2 Campbell Allotment (#11306)**

Project Name	Project Number	Condition	Project Needs
Echave Reservoir # 2	720109	Good	Remove fence around reservoir, retain adjacent corral.
Campbell Reservoir	720637	Fair	Bentonite
Five Points Reservoir	720639	Fair	Bentonite
Larribeau Reservoir	720739	Poor	Bentonite
Pole Creek Well	721412	Failure	Remove and rehabilitate area
Parson Reservoir	721515	Good	Bentonite
No Crossing Corral	722010	Unknown	Unknown
Big Antelope Corral	722011	Unknown	Unknown
Horse Hill Reservoir	721413	Fair	Bentonite

**Table 6.3 Louse Canyon Community Allotment (#01307)**

Project Name	Project Number	Condition	Project Needs
Steer Canyon Pipeline	720857	Fair	Replace float valves and wildlife ramps
Rawhide/Steer Canyon Pipeline	720936	Fair	Replace float valves and wildlife ramps
Exchange Spring Pipeline	722050	Fair	Re-alignment, some reconstruction, and wildlife ramps
New Road Spring	722052	Fair	Repair outlet and fit

Project Name	Project Number	Condition	Project Needs
			float valve
Lower Exchange Spring	723788	Fair	Remove trash and replace float valve
Pedroli Spring	724215	Poor	Remove trash and replace or remove trough
Edge Spring	724795	Poor	Remove and abandon
Dilemma Spring	724803	Poor	Reconstruct
Indian Spring	724805	Failure	Remove and abandon
Little Bog Spring	724806	Poor	Replace trough or remove
Spare Spring	724810	Failure	Remove trash and abandon
Flint Spring	724811	Unknown	Unknown
Lone Tree Spring	724812	Failure	Reconstruct
Cavieta Reservoir	725686	Fair	Repair dam face
Jack Cr. Spring	No File	Poor	Remove trash
Unknown Spring	No File	Poor	Remove and abandon
Lime Spring	714814	Poor	Replace inlet

**Table 6.4 Star Valley Community Allotment (#01402)**

Project Name	Project Number	Condition	Project Needs
Cairn Spring	720057	Poor	Reconstruct
Star Valley Reservoir	720062	Good	Bentonite
Oregon Butte Spring	720171	Poor	Reconstruct
Tent Cr. Corral and House	721930	Poor	Remove and abandon
Stoney Corral Cabin	721931	Failure	Remove and abandon
Twin Butte Reservoir	722086	Fair	Bentonite
Airplane Reservoir	724002	Fair	Bentonite
Freeway Reservoir	724783	Good	Remove and rehabilitate area

**Table 6.5 EXCLOSURES, Summary and Recommendations**

<b>Project Name</b>	<b>Allotment Name</b>	<b>Project Number</b>	<b>Condition</b>	<b>Recommendation</b>
Warm Springs Exclosure	Ambrose Maher	723667	Good	Keep and maintain
Climax Exclosure	Campbell	721552	Good	Keep and maintain
Coyote Holes Habitat Exclosure	Campbell	722040	Good	Reconstruct and maintain for recreational fishing.
Bell Spring Wildlife Exclosure	Campbell	723606	Good	Keep outer exclosure, remove downed wire and posts in interior.
Sacramento Hill Test Plot Exclosure	Campbell	725645	Good	Keep
Pedroli Spring Exclosure	Louse Canyon Community	Unknown	Poor	Remove and abandon
Upper Guadalupe Spring Wildlife Exclosure	Louse Canyon Community	724029	Good	Keep and build new fence corners
New Road Spring Exclosure	Louse Canyon Community	724030	Poor	Remove and abandon
Rawhide Exclosure	Louse Canyon Community	725651	Poor	Remove and abandon
Oregon Butte Spring Wildlife Exclosure	Star Valley Community	725711	No longer exists	Remove from files